

H8SX Series, 1638 Group, UBC, Boundary scan FP-120B; Vcc= 3.0 to 3.6 volts, Temp= -20 to 75 C; Package: PLQP0120LA-A

Manufacturers	Renesas Technology Corp
Package/Case	LQFP-120
Product Type	MCU
RoHS	
Lifecycle	



Images are for reference only

Please submit RFQ for R5F61638N50FPV or [Email to us: sales@ovaga.com](mailto:sales@ovaga.com) We will contact you in 12 hours.

[RFQ](#)

General Description

Ovaga has a large stock of R5F61638N50FPV MCU from Renesas Technology Corp and we guarantee that they are original, brand new parts sourced directly from Renesas Technology Corp. We can provide quality testing reports for R5F61638N50FPV upon your request. To obtain a quote, simply fill in the required quantity, contact name, and email address in the quick quote form on the right. Our sales representative will contact you within 12 hours.



Related Products




[R5F21246SNFP](#)

Renesas Technology Corp
QFP48




[R5F21368CNFP](#)

Renesas Technology Corp
64-LQFP



[R5F21134FP](#)

Renesas Technology Corp
QFP-32



[R5S77641P300BG](#)

Renesas Technology Corp
BGA



[R5S77641N300BG](#)

Renesas Technology Corp
BGA



[R5F562TAAAFP#V1](#)

Renesas Technology Corp
RX62T32Bit100Mhz



[R5F56218BDFP#V0](#)

Renesas Technology Corp

100-LQFP



[R5F52306ADFM#30](#)

Renesas Technology Corp

64-LQFP